

# PPS3210-MO

## 高解析度三組獨立輸出 可程式直流電源供應器 使用手冊



**BK PRECISION**  
ELECTRONIC TEST INSTRUMENTS

## 法律事項聲明

本使用手冊內容如有變更，恕不另行通知。

本公司並不對本使用手冊之適售性、適合作某種特殊用途之使用或其他任何事項作任何明示、暗示或其他形式之保證或擔保。故本公司將不對手冊內容之錯誤，或因增減、展示或以其他方法使用本手冊所造成之直接、間接、突發性或繼續性之損害負任何責任。

台灣百科精密儀器股份有限公司  
新北市深坑區北深路三段 250 號 3 樓

版權聲明：著作人—台灣百科精密儀器股份有限公司—西元 2005 年，**版權所有，翻印必究**。

未經本公司同意或依著作權法之規定准許，不得重製、節錄或翻譯本使用手冊之任何內容。

# 保 證 書

台灣百科精密儀器股份有限公司秉持「品質保證可靠，服務永遠周到」之信念，對所製造及銷售之產品自交貨日起一年內，保證正常使用下產生故障或損壞，負責免費修復。

保證期間內，對於下列情形之一者，本公司不負免費修復責任，本公司於修復後依維修情況酌收費用：

- (1) 非本公司或本公司正式授權代理商直接銷售之產品。
- (2) 因不可抗拒之災變，或可歸責於使用者未遵照操作手冊規定使用或使用人之過失，如操作不當或其他處置造成故障或損壞。
- (3) 非經本公司同意，擅自拆卸修理或自行改裝或加裝附屬品，造成故障或損壞。

保證期間內，故障或損壞之維修品，使用者應負責運送到本公司或本公司指定之地點，其送達之費用由使用者負擔。修復完畢後運交使用者(限台灣地區)或其指定地點(限台灣地區)之費用由本公司負擔。運送期間之保險由使用者自行向保險公司投保。

台灣百科精密儀器股份有限公司

新北市深坑區北深路三段250號3樓  
服務專線：(02)7741-6699轉298  
傳真電話：(02)7741-6686

電子郵件：[fae@bkprecision.com.tw](mailto:fae@bkprecision.com.tw)  
網址：<http://www.bktw.com.tw/>

---

**※※※ 儲存. 搬運. 維護. 處置 ※※※**

---

**儲存**

本裝置不使用時，請將本裝置適度包裝，置於符合本裝置保存環境下進行儲存。(若保存環境良好，可免除包裝作業)。

**搬運**

本裝置在搬運時，請使用原有包裝材料包裝後再行搬運。若包裝材料遺失，請使用相當的緩衝材料進行包裝並註明易碎、防水等符號再行搬運，以防止搬運過程中造成本裝置損壞。

本裝置屬精密器具，請儘量使用合格的運輸工具進行運輸。並儘量避免重落下等易損害本裝置的動作。

**維護**

本裝置內無任何一般使用者可維護操作項目。(說明書中註明者除外)當本裝置發生任何使用者判斷異常時，請連絡本公司或各代理商，切勿自行進行維護作業，以免發生不必要的危險，亦可能對本裝置造成更大損壞。

**處置**

本裝置不使用時，請依貴公司的報廢處理程序進行處理，或依貴公司所在地的合法程序進行本裝置處理。切勿任意遺棄以免造成環境破壞。

---

# 目 錄

---

<b>1.</b>	<b>前言.....</b>	<b>1-1</b>
1.1	產品概要.....	1-1
1.2	特點.....	1-1
<b>2.</b>	<b>規格.....</b>	<b>2-1</b>
<b>3.</b>	<b>使用前注意事項.....</b>	<b>3-1</b>
3.1	使用前附件確認.....	3-1
3.2	使用說明.....	3-1
3.3	使用周圍環境.....	3-1
3.4	保存.....	3-1
3.5	電源電壓.....	3-2
3.6	保險絲.....	3-2
3.7	預熱時間.....	3-2
3.8	測試終止.....	3-2
<b>4.</b>	<b>面板說明.....</b>	<b>4-1</b>
4.1	PPS3210-MO 面板說明 .....	4-1
4.1.1	前板說明.....	4-2
<b>5.</b>	<b>簡易操作設定.....</b>	<b>5-1</b>
5.1	設定電壓.....	5-1
5.2	設定電流.....	5-1
5.3	過電壓保護 OVP.....	5-1
5.4	過電流保護 OCP .....	5-2
5.5	電壓輸出時可由飛梭旋鈕控制.....	5-2
<b>6.</b>	<b>遠端界面通信協定及封包模式.....</b>	<b>6-1</b>
6.1	前言.....	6-1
6.2	參數定義.....	6-1
6.3	錯誤/事件列表.....	6-2
6.4	BK PRECISION LPS & PPS 系列相容的協定.....	6-3
6.5	SCPI 相符合的資訊 .....	6-7
6.5.1	SCPI 常見指令 .....	6-7
6.5.2	SCPI 指令副系統 .....	6-8
6.6	狀態定義的規則.....	6-19
<b>7.</b>	<b>校正步驟.....</b>	<b>7-1</b>
7.1	校正儀器需求.....	7-1
7.1.1	如何進入 CH1 校正模式：同時按下”飛梭旋鈕” + 數字鍵”1”.....	7-1
	CH1 電壓校正接線圖 .....	7-1

---

CH1 電流校正接線圖 .....	7-2
7.1.2 如何進入 CH2 校正模式：同時按下”飛梭旋鈕” + 數字鍵”2” .....	7-3
CH2 電壓校正接線圖 .....	7-3
CH2 電流校正接線圖 .....	7-4
7.1.3 如何進入 CH3 校正模式：同時按下”飛梭旋鈕” + 數字鍵”3” .....	7-5
CH3 電壓校正接線圖 .....	7-5
CH3 電流校正接線圖 .....	7-6
<b>8. 附件一覽表.....</b>	<b>8-1</b>

# 1. 前言

## 1.1 產品概要

PPS3210-MO 是三組輸出及可程式的直流電源供應器，PPS3210-MO 是使用 16bit 的 D/A, A/D Converter，電壓解析度為 1mV、電流解析度為 100uA。獨立的三組電源共提供了 222W 的功率輸出，兩組 0~32V/3A、一組 0~15V/5A；其中的 0~15V/5A 在 30W 的定功率輸出前提下；可隨客戶任意調整輸出電壓及電流，有別於其他傳統式的電源供應器只有固定電壓及電流。兩組 0~32V 的電壓輸出可依需求轉換成串、並聯模式，並可設定 Tracking 模式，讓你在電路應用上更加方便、靈活。

PPS3210-MO 增加了飛梭旋鈕及數字功能鍵，在設定上更加的容易、快速。可將設定值直接儲存於記憶體(100 組)中，增添操作上的方便。另有計時器 (1 sec ~ 100 hours) 功能，來控制輸出何時 OFF，可用於燒機室的安全性考量及電鍍方面的運用。OVP、OCP 保護可由面板控制及監控，且有按鍵鎖功能，使客戶不輕易動到原設定值。當電源及負載變動時，0.01% load and line regulation 及小於 50uS 的反應時間，這兩項功能使 PPS3210-MO 有極穩定的輸出，50msec 的平均量測速度，可讓生產線的產量大為增加。

## 1.2 特點

### 1. 三組輸出：

**Voltage Ranges** : 0 ~ 32V (CH1&CH2) / 0 ~ 15V (CH3)

**Current Ranges** : 0 ~ 3A (CH1&CH2) / 0 ~ 5A (CH3)

**Power Ranges** : 0 ~ 96W (CH1&CH2) / 0 ~ 30W (CH3)

第三組輸出為定功率輸出，共有 30W 的功率可設定電壓及電流，例如設定 15V/2A 或是 6V/5A 都可以設定，只要輸出功率為 30W 以下，不超過電壓及電流的最大值，都可自由設定。

### 2. 數位式飛梭旋鈕、數字鍵、功能鍵的設定

數位式的飛梭旋鈕可以瞬間改變電壓的設定，模擬電壓電流劇升劇降的狀態，對於觸發電路的測試提供了很好的解決方法。數字鍵功能使的使用者更加容易、快速的設定，不用再忍受傳統式的 VR 類比調整。以功能鍵來切換各種模式時，讓整個操作更加人性化、更容易上手。

### 3. 精準的電壓及電流量測：

除了準確的輸出之外，PPS3210-MO 本身還提供了電壓及電流的精準量測，讓

你省下了額外的量測儀器經費及空間。

#### 4. 記憶體及計時器功能：

總共 100 組的記憶體，讓生產線人員不需記憶太多的設定值，只要將設定值儲存於 PPS3210-MO 之中，就可以隨時呼叫出來，省去了文件的規格記錄。計時器功能讓機器於燒機室燒機不需要隨時注意時間，時間一到馬上停止輸出，兼顧了安全性及靈活性。用在電鍍方面的應用，不管是時間的掌控或是電流的解析度，都可完全符合客戶的需求。

#### 5. 過電壓、過電流保護及按鍵鎖功能：

OVP、OCP 保護不僅可以保護待測物，更提供了使用者在實驗上的安全性。按鍵鎖功能讓你在設定完之後，不會因為外部的干擾及誤動作而改變了原有的設定值。

#### 6. 串、並聯模式：

使用串聯模式，可使原來的 CH1/CH2 的 32V 經由串聯模式可拉高至 64V 輸出，並且可以使用正、負電源，最常用在 OPA 的正、負電源使用上。使用並聯模式，可使原來的 CH1/CH2 的 3A 經由並聯模式可拉高至 6A 輸出。不管是串聯或是並聯模式都是由機器內部的 Relay 來控制，完全不需要外部的接線。

#### 7. Dual Tracking：

使用 **Dual Tracking** 模式，只要設定 CH1 輸出電壓及電流，內部程式自動就將 CH2 的設定值設定的和 CH1 一樣。此用途多用在需兩組相同的電壓輸出，或是需同時測試兩個相同待測物。

## 2. 規格

Model	PPS3210-MO	
Channel NO.	CH1 & CH2	CH3
Output Voltage	0~32V	0~15V
Output Current	0~3A	0~5A
Output Power (CH3 Auto Ranging)	96W	30W
<b>Line Regulation ±(% of output +offset)</b>		
Voltage	0.01% + 2mV	
Current	0.01% + 300uA	
<b>Load Regulation ±(% of output +offset)</b>		
Voltage	≤ 3mV	≤ 5mV
Current	0.01% + 300uA	
<b>Ripple and Noise ( 20Hz ~ 20MHz )</b>		
Normal Mode Voltage	700uVrms / 7mVpp	1mVrms / 20mVpp
Normal Mode Current	< 1mA	< 5mA
<b>Resolution</b>		
Programming	1mV / 100uA	
Readback	1mV / 100uA	
<b>Programming Accuracy ±(% output +offset)</b>		
Voltage	0.01% + 5mV	
Current	0.01% + 1mA	0.01% + 2mA
<b>Readback Accuracy ±(% output +offset)</b>		
Voltage	0.01% + 5mV	
Current	0.01% + 1mA	0.01% + 2mA
<b>Temperature Coefficient per°C ±(% output +offset)</b>		
Voltage	< 0.01% + 3mV	
Current	< 0.02% + 2mA	
<b>Tracking Accuracy ±(% of output +offset)</b>		
Voltage	0.02% + 10mV	
<b>Transient Response Time</b>		
< 50uS		
<b>Stability, constant output &amp; temperature ±(% of output +offset), 8hrs</b>		
Voltage	< 0.02% + 2mV	
Current	< 0.01% + 1mA	

<b>Voltage Programming Speed</b>	
Rising Time at Full Load	3mSec
Rising Time at No Load	3mSec
Falling Time at Full Load	8mSec
Falling Time at No Load	250mSec
<b>General</b>	
AC Line Input Voltage Ranges	115/220 VAC $\pm$ 10% ( 50/60Hz )
Temperature Ratings	Operating( 0°C ~ 40°C ) , Storage (- 10°C ~ 70°C)
Common-Mode Voltage	$\pm$ 240Vdc
Dimensions ( W×H×D )mm	( 216 × 135 × 432 )
Weight	9 kg

### PPS3210-MO 特點說明：

- LCD 讀值顯示、三組電源獨立輸出且同時顯示讀值。
- CH3 為定功率輸出。
- Low Ripple、Low Noise。
- 數字鍵、功能鍵設定；有別於傳統的電源供應器。
- 單機具儲存及呼叫功能(100 組)。
- 計時器功能(1 sec ~ 100 hours)。
- 精準的電壓及電流量測。
- 過電壓保護、過電流保護及按鍵保護功能。
- 串、並聯模式。
- Dual Tracking 模式。
- 每一筆量測時間平均為 50mSec。
- 標準的 RS232、USB 介面。
- Remote Sense 電壓補償
- 選購介面：GPIB+LAN+I/O Port。

## 3. 使用前注意事項

### 3.1 使用前附件確認

收到本機後，請依以下所示事項確認，以維護您的權益。

1. 產品外觀是否破損、刮傷等不良現象。
2. 標準附件如附件一覽表 7-1 所列，請確認是否有遺漏附件。  
※ 若有上述之情形，請儘早告之本公司，以便立即為您服務。

### 3.2 使用說明

本機為一精密儀器，為防止不當的操作以及任意的使用造成本機的損壞，請務必先詳讀本說明書；且為維持準確度，請每一年送校一次。

### 3.3 使用周圍環境

1. 請勿將本機放置得多灰塵、多震動、日光直射及腐蝕氣體下使用。並請在周圍溫度 0~40°C，相對濕度 20%~80%的範圍內使用，如果溫度範圍超過 40°C時請先暫停使用，使其溫度下降至正常溫度後再使用，請務必檢測以免溫度過高造成主機損壞。
2. 本機為防止內部溫度上升，於背板內裝有一組吹出式冷卻風扇，所以請注意風扇周圍的通風，使其與背後的牆壁或物品距離 10 cm以上，並請勿阻塞通風孔，以保持良好之準確度。
3. 本機雖已針對交流電源雜音防止十分注意，但亦請儘可能在雜音小的環境下使用，在無法避免雜音的情形下，請加裝電源濾波裝置使用。

### 3.4 保存

本機的保存溫度範圍為-10°C~70°C，相對濕度應為 80% RH 以內，若長時間不使用，請以原包裝或其它類似包裝保存於無日光直射且乾燥的地方，以確保再使用時有良好之準確度。

### 3.5 電源電壓

本機所使用交流電源為 115V/220V 可切換式，所以在接上電源之前，請務必確認電源開關在 OFF 狀態下，使用電源與底板電壓選擇相同，電源頻率請使用 50Hz 或 60Hz。

### 3.6 保險絲

本機背板裝有一電源保險絲，更換保險絲時請注意：

1. 請務必先將電源開關 OFF，並拔掉電源線後再進行。
2. 保險絲之檢查只用目視不能確定,測試其阻值在 15Ω 以下則正常。
3. 更換保險絲時，將保險絲座以一字起子推出之後，將新的保險絲換上。

標示	中心值	使用範圍	保險絲
115	115V	100V~125V	慢熔
220	220V	200V~250V	慢熔

**警告：**

為確保防範火災之發生，在換保險絲時，  
請務必使用一形式及同一規格之保險絲。

### 3.7 預熱時間


本機的所有功能在電源開啟時同時動作，但為達到規格內之準確度，請預熱 30 分鐘以上。

### 3.8 測試終止

當測試已告一段落而不需再使用時，或是本機不再使用狀態下，以及在使用中而需離開時，請務必將電源開關切在 OFF 的地方，即關掉電源。

## 4. 面板說明

### 4.1 PPS3210-MO 面板說明




### 4.1.1 前板說明


- (1) 顯示器：  
為 20\*4 藍色背光 LCD。
- (2) 飛梭旋鈕(ENTER)：  
飛梭旋鈕本身可以調整電壓或電流之外，還可以輕壓來當作 ENTER 的功能。
- (3) M：  
Memory 功能，按此鍵就進入記憶體畫面，可使用飛梭或是數字鍵來選擇那一組需儲存、或呼叫功能，需搭配使用(呼叫 RECALL 鍵)、(儲存 STORE 鍵)。
- (4) CH：  
作為 CH1/CH2/CH3 切換選擇。
- (5) ON/OFF：  
作為輸出 ON、OFF 切換，電源輸出或是電源關閉。
- (6) 數字鍵：  
按完數字鍵的數字之後，再搭配”V”或”A”就可以設定電壓或電流。
- (7) ►(STORE)：  
當電壓輸出時，當做游標，可往右移動游標至所需的位數，再利用飛梭旋鈕調整數值。當進入 Memory 功能時，此鍵當作儲存(STORE)的功用。
- (8) ◀(RECALL)：  
當電壓輸出時，當做游標，可往左移動游標至所需的位數，再利用飛梭旋鈕調整數值。當進入 Memory 功能時，此鍵當作呼叫(RECALL)的功用。
- (9) DISP：  
作為切換視窗之用，可顯示電壓及電流；或是顯示功率及阻抗。
- (10) V(電壓)：  
按完數字鍵之後，再搭配”V”鍵，就可以完成電壓設定。
- (11) A(電流)：  
按完數字鍵之後，再搭配”A”鍵，就可以完成電流設定。
- (12) Config(設定)：(PS：設定完之後，必須選擇 16. Back Main Menu，設定值才會儲存。)

設定選項共有 16 項：


1. Timer：計時器。初始值為 OFF；按一下飛梭旋鈕之後進入 Timer 的設定畫面。




- A. 旋轉飛梭旋鈕或是 ◀▶ 來移動游標，再按數字鍵設定時間；  
TIMER：00：00：00 依序為小時：分鐘：秒。
  - B. 按“CH”鍵來選擇 CH1/CH2/CH3，LCD 的左半邊有 ← 可指示，按一下飛梭旋鈕之後，各 CH 可更改為 ON。
  - C. 最後按下“ON/OFF”鍵，開始 Timer 功能。
  - D. 如需暫停 TIMER 功能，按住飛梭旋鈕 + CLEAR 鍵；如需恢復 TIMER 狀態的話，再做一次既可。
2. TRACKING：同步。初始值為 OFF；按一下飛梭旋鈕之後，狀態更改為 ON。跳出 Config(設定)畫面之後，此時再設定 CH1 輸出電壓及電流，CH2 的設定值就會完全和 CH1 一樣。




3. OVP setting：過電壓保護。按一下飛梭旋鈕之後，進入 OVP 的設定畫面。按”CH”鍵選擇那一 Channel，共有 CH1/CH2/CH3 可供選擇 (LCD 的左半邊有→可指示)，按下 ON/OFF 鍵選擇是否啟動，再直接輸入設定的電壓，記得要按下飛梭旋鈕設定值才會儲存，OVP 功能就會啟動。




4. OCP setting：過電流保護。按一下飛梭旋鈕之後，進入 OCP 的設定畫面。按”CH”鍵選擇那一 Channel，共有 CH1/CH2/CH3 可供選擇 (LCD 的左半邊有→可指示)，按下 ON/OFF 鍵選擇是否啟動，再直接輸入設定的電流，記得要按下飛梭旋鈕設定值才會儲存，OCP 功能就會啟動。




5. Baud rate：傳輸速率。RS232 的 Baud rate 速率選擇，有 1200、2400、4800、9600、19200、38400。按一下飛梭旋鈕來選擇速率。




6. Interface：傳輸介面。按一下飛梭旋鈕來選擇 RS-232、USB、GPIB(選購介面)、ETHNET(Ethernet 介面，選購介面)。




7. DHCP：LAN PORT 專用。初始值為 OFF；按一下飛梭旋鈕之後狀態為 ON。ON 之後可由 SEVER 端獲得一個動態 IP 位址。




8. IP\*\*\*.\*\*\*.\*\*\*.\*\*\*：設定機器 IP 位址。按一下飛梭旋鈕之後，按下數字鍵，就可更改機器 IP 位址。




9. BEEP：蜂鳴器。按一下飛梭旋鈕來選擇關閉、開啟。




10. Key lock：按鍵鎖功能。初始值為 OFF；按一下飛梭旋鈕之後狀態為 ON，整個指令無法按鍵輸入，要解除狀態按住飛梭 + CLEAR 鍵既可。




11. Parallel out：並聯輸出。初始值為 OFF；按一下飛梭旋鈕之後，狀態更改為 ON。跳出 Config(設定)畫面之後，此時的 CH1 & CH2 內部正端相連、負端相連，原本任一 CH 可輸出 32V/3A 的電流，如今已可以輸出 32V/6A。




12. Serial out：串聯輸出。初始值為 OFF；按一下飛梭旋鈕之後，狀態更改為 ON。跳出 Config(設定)畫面之後，此時的 CH1 正端和 CH2 負端短路，當作 COM 點，則 CH2 正端對 COM 有 +32V 的可設定電壓、CH1 負端對 COM 有 -32V 的可設定電壓。而 CH2 正端對 CH1 負端則有 64V 的電壓差。




13. Address： GPIB 位址設定。00 ~ 31 的可設定範圍，數字輸入之後，記得按一下飛梭旋鈕儲存。




14. Hot Key：快速功能鍵。初始值為 OFF；按一下飛梭旋鈕之後，狀態更改為 ON。跳出 Config(設定)畫面之後，此功能等於將 Memory 內的第 0 ~ 9 組，由數字 0 ~ 9 代表，只要按下數字鍵就可以呼叫出 Memory 內第 0 ~ 9 組的設定資料。




15. Initial Mode：記憶住關機前的狀態。初始值為 OFF；按一下飛梭旋鈕之後，狀態更改為 ON。狀態為 ON 時，它會記憶住關機前的所有設定，等待下次開機時，就會依照之前的儲存狀態，再還原出來。




16. Out Mode：輸出模式。初始值為 Single；按一下飛梭旋鈕之後，狀態更改為 Multi。Single 為單一組輸出模式。Multi 為三組輸出模式。選擇 Single；跳出 Config(設定)畫面之後，當按下 ON/OFF 鍵，一次一組輸出。選擇 Multi；跳出 Config(設定)畫面之後，按下 ON/OFF 鍵，一次三組輸出。



17. Factory Preset：恢復成原廠設定。當按下此鍵之後畫面出現 ON/OFF KEY TO REPLACE SETTING，假如再按下” ON/OFF “鍵，就會將機器改為出廠的初始值，如果不需要變更，請按” CLEAR “跳出。



18. Back Main Menu：跳離 Config 的功能畫面；並儲存設定值。



- (13) . (LCL)：

當作小數點之用，或是當進入 REMOTE 連線狀態之後，按下此鍵也可以恢復成 LOCAL 模式(單機操作模式)。

- (14) CLEAR(ESC)：

清除數字的設定，或是跳至上一層畫面。

- (15) 電源開關(POWER ON/OFF)


電源開關 ”■” 為 OFF, ”■” 為 ON,而在開啟前請先參閱”使用前注意事項。

(16) CH1/CH2/CH3 電源輸出端：

請依照前板規格標示，並注意其正、負端極性。

(17) GND：

接至電源地端。請注意其電源線是否為三叉接頭，否則此孔無接地作用。



後板說明

(18) AC 電源輸入：

電源連接用插座，適用於 115V/220V。

(19) Fuse 保險絲：

為電源用保險絲，切換開關設為 115V 時，使用 5A 慢溶保險絲；設為 220V 時，使用 2.5A 慢溶保險絲。


(20) Remote Sense/Local Sense 切換指撥開關：

當切為 ON 時；為 Local Sense 狀態，也就是內部正端和 +Sense 接在一起；負端和 -Sense 接在一起。切為 OFF 時；為 Remote Sense 狀態，此時搭配  $\pm$ Sense 就具有電壓補償的功能。

(21) CH1  $\pm$ S / CH2  $\pm$  S :

當指撥開關切為 OFF 時；為 Remote Sense 狀態，此時就具有電壓補償的功能。接線方法如下：CH1 的 +Sense 和 CH1 正端接至待測物的正端；CH1 的 -Sense 和負端接至待測物的負端；此時的接法可以補償線路的傳導損失。CH2 接線方式同 CH1。

(22) RS232 傳輸介面：使用 Pin-To-Pin cable 與 PC 連接，接腳圖如下：



(23) USB 傳輸介面。

(24) 115V/220V 電源切換開關：(在機器的下方偏前板位置)。

(25) 散熱風扇：

會依照吃載電流的大小，來調整風扇的轉速，是智慧型的風扇設計。

(26) 選購介面：

有 GPIB+LAN+I/O Port 等介面。

## 5. 簡易操作設定

### 5.1 設定電壓

按 "CH" 鍵選擇需修改那一 Channel，共有 CH1/CH2/CH3 可供選擇 (LCD 的左半邊有 \* 可指示)，再按數字鍵直接輸入設定的電壓，最後按 "V" 輸入，電壓設定值就會直接更改完成。

	TIMER	TRK	LOCK	RMT	P/S	
	30V					
CH1	OFF*	30.00V		3.000A		OVP1
CH2	OFF	10.01V		3.000A		OCP1
CH3	OFF	5.00V		3.000A		OVP2
						OCP2
						OVP3
						OCP3

### 5.2 設定電流

按 "CH" 鍵選擇需修改那一 Channel，共有 CH1/CH2/CH3 可供選擇 (LCD 的左半邊有 \* 可指示)，再按數字鍵直接輸入設定的電流，最後按 "A" 輸入，電流設定值就會直接更改完成。

	TIMER	TRK	LOCK	RMT	P/S	
	3A					
CH1	OFF*	30.00V		3.000A		OVP1
CH2	OFF	10.01V		3.000A		OCP1
CH3	OFF	5.00V		3.000A		OVP2
						OCP2
						OVP3
						OCP3

### 5.3 過電壓保護 OVP

按 "Config" 鍵，進入 Configuration 畫面，旋轉飛梭旋鈕或是 ◀▶ 來移動游標至 3.OVP setting，按一下飛梭旋鈕之後，進入 OVP 的設定畫面。按 "CH" 鍵選擇那一 Channel，共有 CH1/CH2/CH3 可供選擇 (LCD 的左半邊有 → 可指示)，按下 ON/OFF 鍵選擇是否啟動，再直接輸入設定的電壓，記得要按下飛梭旋鈕設定值才會儲存。

## 5.4 過電流保護 OCP

按“Config”鍵，進入 Configuration 畫面，旋轉飛梭旋鈕或是◀▶來移動游標至 4.OCP setting，按一下飛梭旋鈕之後，進入 OCP 的設定畫面。按”CH”鍵選擇那一 Channel，共有 CH1/CH2/CH3 可供選擇 (LCD 的左半邊有→可指示)，按下 ON/OFF 鍵選擇是否啟動，再直接輸入設定的電流，記得要按下飛梭旋鈕設定值才會儲存。

## 5.5 電壓輸出時可由飛梭旋鈕控制

當電壓已經輸出時，可以由飛梭旋鈕來直接控制電壓的增減。步驟如下：當電壓已經輸出時，按下◀或▶，此時游標會出現，再調整飛梭旋鈕就可以增減電壓，如要改變 Channel，只要按下”CH”鍵就可以了。此功能可以讓你即時觀看電壓的變化。

	TIMER	TRK	LOCK	RMT	P/S
CH1	CV *	1.99V		0.000A	OVP1
CH2	OFF	10.01V		3.000A	OCP1
CH3	OFF	5.00V		3.000A	OVP2
					OCP2
					OVP3
					OCP3

## 6. 遠端界面通信協定及封包模式

通信協定包括BK PRECISION指令，SCPI指令和低錯誤的協定。

### 6.1 前言

SCPI 界面選擇使你能夠透過電腦的 IEEE-488.2 GPIB 或 RS-232 界面去操作你的電源供應器，並允許遠端程式控制和監控。

SCPI IEEE-488.2 版本支持多組的電源控制(允許控制最多 32 組電源)。

### 6.2 參數定義

Type	Valid arguments
<boolean>	“ON” or 1, “OFF” or 0
<NR1>	The data format <NR1> is defined in IEEE-488.2 for integers. Zero, positive and negative integer numeric values are valid data.
<NRf>	The data format <NRf> is defined in IEEE-488.2 for flexible Numeric Representation. Zero, positive and negative floating point numeric values are some examples of valid data.
<string>	Characters enclosed by single or double quotes
<NL>	New line, Hex code is 0x0Ah
<Rtn>	Return, Hex code is 0x0Dh
<END>	End or identify

**Note:** All commands shall be ended with the <NL> and <Rtn>. And there shall be a space between the command and the parameter.

For example, to set the GPIB address of 10 to a PPS3210-MO. The command line is as follows:

**ADDR 10<NL><Rtn>**

**Note:** The <NL> and <Rtn> are not presented in the following examples and command descriptions. However, users shall add them to the end of each command when doing the coding.

## 6.3 錯誤/事件列表

SCPI界面能夠提供一個錯誤/事件清單。這個錯誤/事件清單可以多達10個。我們可以經由 `error ?`指令以(先進先出)模式來讀取系統裡相關訊息。讀取的動作會清除掉錯誤/事件清單中的暫存空間中先前的資料，經由\* `CLS`指令來清除所有錯誤/事件清單暫存記憶

### 錯誤 敘述

```
=====
```

-000	No error
-002	GET not allowed
-003	Parameter not allowed
-005	Command Header Error
-010	Numeric data error
-011	Invalid character in number
-013	Too many digits
-014	Numeric data not allowed
-016	Invalid suffix
-020	Invalid character data
-030	Invalid expression
-035	Macro parameter error
-056	Missing media
-058	Media full
-059	Directory full
-060	File name not found
-088	Media protected
-089	Expression Error
-100	Program error
-101	Cannot create program
-104	Program currently running
-105	Program syntax error
-106	Program runtime error
-108	Syntax error
-109	Data type error
-110	Input voltage overwrite error
-111	Input current overwrite error

## 6.4 BK PRECISION LPS & PPS 系列相容的協定

Command	Description
ADDRess	set the address of the machine
ADDRess?	return the address current setting
BEEP	set beep on(1) or off(0)
CALi?	calibration procedure
CURR[1]	channel 1 current setting
CURR[1]?	return channel 1 current setting
CURR2	channel 2 current setting
CURR2?	return channel 2 current setting
CURR3	channel 3 current setting
CURR3?	return channel 3 current setting
CURRENT[1]	channel 1 current setting
CURRENT[1]?	return channel 1 current setting
CURRENT2	channel 2 current setting
CURRENT2?	return channel 2 current setting
CURRENT3	channel 3 current setting
CURRENT3?	return channel 3 current setting
HOTKey	set hot key function, on(1) or off(0)
IOUT[1][?]	channel 1 current readback
IOUT2[?]	channel 2 current readback
IOUT3[?]	channel 3 current readback
ISET[1]	channel 1 current setting
ISET[1][?]	return channel 1 current setting
ISET2	channel 2 current setting
ISET2?	return channel 2 current setting
ISET3	channel 3 current setting
ISET3?	return channel 3 current setting
LOCK	set rotary and keypad lock on(1) or off(0)
MODEL?	display model NO
OCP[1]	set channel 1 current protect to off(0) or on(1)
OCP2	set channel 2 current protect to off(0) or on(1)
OCP3	set channel 3 current protect to off(0) or on(1)
OISET[1]	set channel 1 overcurrent protect
OISET[1]?	return channel 1 overcurrent value

---

OISET2	set channel 2 overcurrent protect
OISET2?	return channel 2 overcurrent value
OISET3	set channel 3 overcurrent protect
OISET3?	return channel 3 overcurrent value
OUT[1]	set channel 1 output on(1) or off(0)
OUT2	set channel 2 output on(1) or off(0)
OUT3	set channel 3 output on(1) or off(0)
OVP[1]	set channel 1 voltage protect to off(0) or on(1)
OVP2	set channel 2 voltage protect to off(0) or on(1)
OVP3	set channel 3 voltage protect to off(0) or on(1)
OVSET[1]	set channel 1 overvoltage protect
OVSET[1]?	return channel 1 overvoltage value
OVSET2	set channel 2 overcurrent protect
OVSET2?	return channel 2 overcurrent value
OVSET3	set channel 3 overcurrent protect
OVSET3?	return channel 3 overcurrent value
PARAllel	set parallel output on(1) or off(0)
SERial	set seial output on(1) or off(0)
STATUS?	current NLPS working status
TRACK	set CH2=CH1
VERSION?	display version NO.
VOLT[1]	channel 1 voltage setting
VOLT[1]?	return channel 1 voltage setting
VOLT2	channel 2 voltage setting
VOLT2?	return channel 2 voltage setting
VOLT3	channel 3 voltage setting
VOLT3?	return channel 3 voltage setting
VOLTAGE[1]	channel 1 voltage setting
VOLTAGE[1]?	return channel 1 voltage setting
VOLTAGE2	channel 2 voltage setting
VOLTAGE2?	return channel 2 voltage setting
VOLTAGE3	channel 3 voltage setting
VOLTAGE3?	return channel 3 voltage setting
VOUT[1][?]	channel 1 voltage readback
VOUT2[?]	channel 2 voltage readback
VOUT3[?]	channel 3 voltage readback
VSET[1]	channel 1 voltage setting
VSET[1]?	return channel 1 voltage setting

VSET2	channel 2 voltage setting
VSET2?	return channel 2 voltage setting
VSET3	channel 3 voltage setting
VSET3?	return channel 3 voltage setting

舉例:

#### Q1. 如何設定 GPIB 的位址 ?

ADDR 10	==>	address is 10
ADDRESS 5	==>	address is 5
ADDR 70	==>	address is out of maximum value, refer to error code

#### Q2. 如何設定蜂鳴器?

BEEP 1	==>	triger beep to on
BEEP off	==>	triger beep to off

#### Q3. 如何設定電壓?

VSET 10	==>	set channel 1 voltage to 10V
VSET2 5.123	==>	set channel 2 voltage to 5.123V
VOLT3 3.3V	==>	set channel 3 voltage to 3.3V
VOLTAGE1 35	==>	set channel 1 voltage to 35V is fail, because out of range

#### Q4. 如何讀取電壓設定值?

VSET?	==>	return channel 1 voltage setting
VSET2?	==>	return channel 2 voltage setting

#### Q5. 如何設定電流?

ISET 1.1	==>	set channel 1 current to 1.1A
ISET2 2.1A	==>	set channel 2 current to 2.1A
CURR3 4.3022	==>	set channel 3 current to 4.3022A
CURRENT1 0.250	==>	set channel 1 current to 250mA

#### Q6. 如何讀取電流設定值?

ISET?	==>	return channel 1 current setting
ISET2?	==>	return channel 2 current setting

**Q7. 如何讀取電壓輸出值?**

VOLT3?	==>	return channel 3 voltage output
VOLTAGE1?	==>	return channel 1 voltage output
VOUT2?	==>	return channel 2 voltage output
VOUT?	==>	return channel 1 voltage output

**Q8. 如何讀取電流輸出值?**

CURR3?	==>	return channel 3 current output
CURRENT1?	==>	return channel 1 current output
IOUT2?	==>	return channel 2 current output
IOUT?	==>	return channel 1 current output

**Q9. 如何設定追蹤模式?**

TRACK 1	==>	CH2 = CH1
TRACK ON	==>	CH2 = CH1
TRACK 0	==>	tracking off
TRACK OFF	==>	tracking off

**Q10. 如何設定並聯輸出模式?**

PARA 1	==>	parallel on
PARALLEL ON	==>	parallel on
PARA 0	==>	parallel off
PARALLEL OFF	==>	parallel off

**Q11. 如何設定串聯輸出模式?**

SER 1	==>	serial on
SERIAL ON	==>	serial on
SER 0	==>	serial off
SERIAL OFF	==>	serial off

**Q12. 如何讀回校正參數?**

CAL?	==>	return the calibration data
CALI?	==>	return the calibration data

**Q13. 如何鎖住按鍵及飛梭旋鈕?**

LOCK 1 ==> lock the keypad and knob  
 LOCK ON ==> lock the keypad and knob

#### Q14. 如何讀回 GPIB 位址?

ADDR?  
 ADDRESS?

## 6.5 SCPI 相符合的資訊

SCPI 可以完全符合所有 IEEE-488.2 和 SCPI 指令(1995)規範. 其中指令都是包含在 SCPI 指令(1995 第二冊規範裡頭).

### 6.5.1 SCPI 常見指令

命令	說明
*CLS	Clear status (include error code)
*CAL?	As same as CALi? command,return calibration parameter
*IDN?	Response: <Manufacturer>, <model>, <serial number>, <firmware type, & version>
*RCL	Recalls settings from memory. Memory locations from 0 to 99 are valid.
*RST	Resets the power supply to its power on state.
*SAV	1. Saves defined parameters 2. Saves current settings to memory. Memory locations from 0 to 99 are valid.
*WAI	Sets the device to wait until all previous commands and queries are complete before executing commands following the *WAI command.

舉例:

#### Q15. 如何儲存電壓/電流的設定值到記憶體中?

\*SAV 15 ==> save current settings to memory location 15  
 SAV 0 ==> save current settings to memory location 0

#### Q16. 如何呼叫記憶體中電壓/電流的設定值?

\*RCL 3 ==> recall setting from memory location 3  
 RCL 120 ==> the data value is invalid

#### Q17. 如何儲存參數?

SAV

\*SAV

**Q18. 軟體重置步驟如何設定?**

\*RST

RST

**Q19. 如何辨認儀器的型號?**

\*IDN?

IDN?

**6.5.2 SCPI 指令副系統**

OUT[n]	on/off subsystem for channel n: 1 - 3
[ STATE/<bool>]	ON/1 (enable) or OFF/0 (disable) output action
:ALL[ STATE/<bool>]	ON/1 (enable) or OFF/0 (disable) output for all channels
:TRACK	enable track mode
:PARAllel	enable parallel mode
:SERial	enable serial mode
:NORMal	resume normal mode
STATus	status subsystem.
[?]	read back machine status
:ERRor[?]	read back machine error code
:CCP[?]	read back Iset DAC value
:CVP[?]	read back Vset DAC value
:MONV[?]	read back Vout DAC value
:MONI[?]	read back Iout DAC value
PROGram	program subsystem
[ STATE/<bool>]	enables/disables program action
[ n]	select [n] page program number, n range from 0 ~ 99
:VSET[n]	volt setting for channel n: 1 - 3
[ level]	voltage level: 0 – 32V for ch1 and ch2, 0 – 15V for ch3
:ISET[n]	current setting for channel n: 1 - 3
[ level]	current level: 0 – 3A for ch1 and ch2, 0 – 5A



:LCD[ STATE/<bool>]	turn ON/1 or OFF/0 the LCD backlight
:FASTREQ[ STATE/<bool>]	ON/1 (enable) or OFF/0 (disable) fast output mode
:HOTKey[ STATE/<bool>]	enable/disable hotkey mode
:LOCK[ STATE/<bool>]	enable/disable keypad and rotary lock
:MONItor[ STATE/<bool>]	enable/disable monitor to send "status" & V/I message(GPIB & LAN not support )
:DHCP[ STATE/<bool>]	enable/disable DHCP mode
:IP	select IP command
[?/ xxx.xxx.xxx.xxx]	return or set up IP address
:Channel[ n]	select channel n: 1 - 3
:ADDReSS	setting address
[?/ n]	return or set up GPIB address n: 1 - 31
:DEFault	resume factory preset(password protected)
:PWD	enter password to verify
:PASSword	:
[ <string>]	the string must be less than 15 characters
:LOCAL ON	disable remote mode and back to local mode
:GPIO	this command is valid when optional card exists
[?/ level]	read or set up level of GPIO pins, level: 0 – 255
:DIRectiOn n	set GPIO pins as input or output (0:input, 1:output), n: 0 – 255

GPIO	Pin 9	Pin 8	Pin 7	Pin 6	Pin 5	Pin 4	Pin 3	Pin 2	Pin 1
Bit	Bit 7	Bit 6	Bit 5	Bit 4	GND	Bit 3	Bit 2	Bit1	Bit 0
Value	128	64	32	16	X	8	4	2	1

MEASure	measure subsystem
:CURRent[n]?	Return the floating point value of the DC output current in amps for channel n: 1 - 3
:VOLTage[n]?	Return the floating point value of the DC output voltage in volts for channel n: 1 - 3
:POWER[n]?	Return DC output power in watts.
:RESistance[n]?	Return DC output impedance in ohms

SOURce]	source subsystem
:CURRent[n]	Sets the floating point value of the DC output current in amps for channel n: 1 - 3
[ level]	current level: 0 – 3A for ch1 and ch2, 0 – 5A for ch3
:PROTection	over current protection (OCP)
[?/ level]	return or set the over current protection trip point in amps.
:TRIGger	trigger current protection
[ state/<bool>]	ON/1 (enable) or OFF/0 (disable) OCP
:VOLTagE[n]	Sets the floating point value of the DC output voltage in volts for channel n: 1 - 3
[ level]	voltage level: 0 – 32V for ch1 and ch2, 0 – 15V for ch3
:PROTection	over voltage protection (OVP)
[?/ level]	return or set the over voltage protection trip point in volts.
:TRIGger	trigger voltage protection
[ state/<bool>]	ON/1 (enable) or OFF/0 (disable) OVP

舉例:

**Q20.** 如何設定追蹤模式?

OUT:TRACK

**Q21.** 如何設定串聯輸出模式?

OUT:SER

OUT:SERIAL

**Q22.** 如何設定並聯輸出模式?

OUT:PARA

OUT:PARALLEL

**Q23.** 如何設定一般輸出模式?

OUT:NORM

OUT:NORMAL

**Q24.** 如何讀回機器本身的狀態?

STATUS?

**Q25. 如何讀回機器本身的錯誤碼?**

STAT:ERR?

STATUS:ERR?

STATUS:ERROR?

STAT:ERROR?

**Q26. 如何讀回設定電壓的 DAC 值?**

STATUS:CVP? ==> read CVP DAC value

**Q27. 如何讀回設定電流的 DAC 值?**

STATUS:CCP? ==> read CCP DAC value

**Q28. 如何讀回電壓的 DAC 值?**

STATUS:MONV? ==> read MONV DAC value

**Q29. 如何讀回電流的 DAC 值?**

STATUS:MONI? ==> read MONI DAC value

**Q30. 如何設定三個通道同時輸出?**

OUT:ALL 1 ==> tri-channel output is ON

OUT:ALL OFF ==> tri-channel output is OFF

**Q31. 如何設定計時器?**

TIMER 00:10:00 ==> set up the timer to run for 10 minutes

TIM 99:59:59 ==> set up the timer to run 99 hours 59 minutes 59 seconds and then stop

**Q32. 如何啟動計時器?**

TIMER ON

TIM ON

**Q33. 如何關閉計時器?**

TIMER OFF

TIM OFF

**Q34. 如何讀取計時器參數?**

TIMER?

TIM?

### Q35. 如何設定程式?

step 1: PROG 10	==>	select program number 10, program number shall be in 0 ~ 99.
step 2: PROG:VSET1 16V	==>	set output voltage to 16v for ch1
step 3: PROG:VSET2 25V	==>	set output voltage to 25v for ch2
step 4: PROG:VSET3 3.3V	==>	set output voltage to 3.3v for ch3
step 5: PROG:ISET1 1A	==>	set output current up to 1A for ch1
step 6: PROG:ISET2 2A	==>	set output current up to 2A for ch2
step 7: PROG:ISET3 3.3A	==>	set output current up to 3.3A for ch3
step 8: PROG:TIMER:00:05:00	==>	set up the run-time to 5 minutes
step 9: PROG:NEXT:NEXT	==>	next step is the next program, program number 11 in this example
:		
:		

### Q36. 如何儲存程式?

PROGRAM:SAV

PROG:SAVE

### Q37. 如何開始程式?

PROG n	==>	select program page number n: 0 ~ 99
PROGRAM ON	==>	start running the program n specified in the above command

### Q38. 如何關閉程式?

PROG OFF

### Q39. 如何讀取程式參數?

PROGRAM?	==>	Return program parameter
PROGRAM:TIMER?	==>	Return timer parameter

### Q40. 如何設定記憶體?

step 1: MEM:1	==>	select memory number: 1
step 2: MEM:VSET 1.5	==>	sets channel 1 voltage to 1.5 V.
step 3: MEM:ISET3 5	==>	sets channel 3 current to 5 A.

**Q41. 如何讀取記憶體參數?**

step 1: MEM 2 ==> select memory number 2  
 step 2: MEM? ==> read back memory NO.2 parameter

**Q42. 如何設定 GPIO 的指向?**

GPIO	Pin 9	Pin 8	Pin 7	Pin 6	Pin 5	Pin 4	Pin 3	Pin 2	Pin 1
Bit	Bit 7	Bit 6	Bit 5	Bit 4	GND	Bit 3	Bit 2	Bit1	Bit 0
Value	128	64	32	16	X	8	4	2	1

Direction: 0 – input; 1 – output

CONT:GPIO:DIRECTION 15 ==> set GPIO pin 1 ~ pin 4 as the outputs and the pin 6 ~ pin 9 as the inputs

CONT:GPIO:DIR 16 ==> set GPIO pin 6 as the output and other pins as the inputs

**Q43. 如何讀回與設定 GPIO 值?**

CONT:GPIO 3 ==> set GPIO pin 1 and pin 2 to output a high level

CONT:GPIO? ==> if return a value of 96, it means the input pin 7 and pin 8 are high and other input pins are low

**Q44. 如何讀取機器編號?**

MEM:SERIAL?

MEMORY:SER?

**Q45. 如何修改機器位址(address)?**

CONTROL:ADDR 23 ==> modify id to 23

CONT:ADDRESS 09 ==> modify id to 9

**Q46. 如何檢查密碼?**

CONT:PASSWORD 123456 ==> enter password to verify

**Q47. 如何進入或是離開監控模式? (GPIB & LAN 不支援)**

CONT:MONITOR ON ==> enter the monitor mode

CONTROL:MONI OFF ==> exit the monitor mode

**Q48. 如何改變通道?**

CONT:CHANNEL 1 ==> change to channel 1

CONT:CH 1 ==> change to channel 1  
 CONTROL:CH 2 ==> change to channel 2

**Q49. 如何進入或是離開閉鎖模式?**

CONT:LOCK ON ==> enter lock mode  
 CONTROL:LOCK OFF ==> exit lock mode

**Q50. 如何進入或是離開快捷鍵模式?**

CONT:HOTK ON ==> enter hotkey mode  
 CONTROL:HOTKEY OFF ==> exit hotkey mode

**Q51. 如何量測電流?**

MEASURE:CURR1? ==> read back current 1 result  
 MEAS:CURRENT3? ==> read back current 3 result  
 MEAS:CURR3? ==> read back current 3 result  
 CURR1? ==> read back current 1 result  
 CURRENT2? ==> read back current 2 result  
 IOUT1? ==> read back current 1 result  
 IOUT2? ==> read back current 2 result

**Q52. 如何量測電壓?**

MEASURE:VOLT1? ==> read back voltage 1 result  
 MEAS:VOLTAGE3? ==> read back voltage 3 result  
 MEAS:VOLT3? ==> read back voltage 3 result  
 VOLT1? ==> read back voltage 1 result  
 VOLTAGE2? ==> read back voltage 2 result  
 VOUT1? ==> read back voltage 1 result  
 VOUT2? ==> read back voltage 2 result

**Q53. 如何量測功率?**

MEASURE:POW1? ==> read back power 1 result  
 MEAS:POWER3? ==> read back power 3 result  
 MEAS:POW3? ==> read back power 3 result

**Q54. 如何量測阻抗?**

MEASURE:RES1? ==> read back resistance 1 result  
 MEAS:RESISTANCE3? ==> read back resistance 3 result  
 MEAS:RES3? ==> read back resistance 3 result

**Q55. 如何設定電壓輸出?**

SOUR:VOLTAGE2 12	==>	set voltage to 12V for channel 2
SOURCE:VOLT1 30	==>	set voltage to 30V for channel 1
VOLT3 10	==>	set voltage to 10V for channel 3
VOLTAGE3 5	==>	set voltage to 5V for channel 3
VSET2 15	==>	set voltage to 15V for channel 2

**Q56. 如何設定電流輸出?**

SOUR:CURRENT2 1	==>	set current to 1A for channel 2.
SOURCE:CURR1 3	==>	set current to 3A for channel 1.
CURRENT3 5	==>	set current to 5A for channel 3.
ISET2 1.5	==>	set current to 1.5A for channel 2.

**Q57. 如何定義過電壓保護?**

SOUR:VOLTAGE3:PROT 12	==>	set over voltage to 12V for channel 3.
SOURCE:VOLT1:PROT 30	==>	set over voltage to 30V for channel 1.
SOUR:VOLT2:PROTECTION 10	==>	set over voltage to 10V for channel 2.
VOLTAGE3:PROT 7	==>	set over voltage to 7V for channel 3.
VOLT2:PROT 18	==>	set over voltage to 18V for channel 2.
VOLT1:PROTECTION 27	==>	set over voltage to 27V for channel 1.
VOLT:PROTECTION 25	==>	set over voltage to 25V for channel 1.
OVSET2 19	==>	set over voltage to 19V for channel 2.

**Q58. 如何定義過電流保護?**

SOUR:CURRENT3:PROT 1.2	==>	set over current to 1.2A for channel 3.
SOURCE:CURR1:PROT 3	==>	set over current to 3A for channel 1.
SOUR:CURR2:PROTECTION 2	==>	set over current to 2A for channel 2.
CURRENT3:PROT 2.7	==>	set over current to 2.7A for channel 3.
CURR2:PROT 1.8	==>	set over current to 1.8A for channel 2.
CURR1:PROTECTION 2.7	==>	set over current to 2.7A for channel 1.
CURR:PROTECTION 2.5	==>	set over current to 2.5A for channel 1.
OISET2 1.9	==>	set over current to 1.9A for channel 2.

**Q59. 如何讀取過電壓保護參數?**

SOUR:VOLTAGE3:PROT?	==>	return over voltage for channel 3.
SOURCE:VOLT1:PROT?	==>	return over voltage for channel 1.
SOUR:VOLT2:PROTECTION?	==>	return over voltage for channel 2.

VOLTAGE3:PROT?	==>	return over voltage for channel 3.
VOLT2:PROT?	==>	return over voltage for channel 2.
VOLT1:PROTECTION?	==>	return over voltage for channel 1.
VOLT:PROTECTION?	==>	return over voltage for channel 1.
OVSET2?	==>	return over voltage for channel 2.

**Q60. 如何讀取過電流保護參數?**

SOUR:CURRENT3:PROT?	==>	return over current for channel 3.
SOURCE:CURR1:PROT?	==>	return over current for channel 1.
SOUR:CURR2:PROTECTION?	==>	return over current for channel 2.
CURRENT3:PROT?	==>	return over current for channel 3.
CURR2:PROT?	==>	return over current for channel 2.
CURR1:PROTECTION?	==>	return over current for channel 1.
CURR:PROTECTION?	==>	return over current for channel 1.
OISET2?	==>	return over current for channel 2.

**Q61. 如何打開或是關閉過電壓保護 (OVP) 功能?**

SOUR:VOLTAGE3:PROT:TRIG ON	==>	enable OVP for channel 3.
SOURCE:VOLT1:PROT:TRIG OFF	==>	disable OVP for channel 1.
SOUR:VOLT2:PROTECTION:TRIG OFF	==>	disable OVP for channel 2.
VOLTAGE3:PROT:TRIG ON	==>	enable OVP for channel 3.
VOLT2:PROT:TRIGGER ON	==>	enable OVP for channel 2.
VOLT1:PROTECTION:TRIG OFF	==>	disable OVP for channel 1.
VOLT:PROTECTION:TRIG OFF	==>	disable OVP for channel 1.
OVP2 ON	==>	enable OVP for channel 2.
OVP3 OFF	==>	disable OVP for channel 3.

**Q62. 如何打開或是關閉過電流保護功能 (OCP)?**

SOUR:CURRENT3:PROT:TRIG ON	==>	enable OCP for channel 3.
SOURCE:CURR1:PROT:TRIG OFF	==>	disable OCP for channel 1.
SOUR:CURR2:PROTECTION:TRIG OFF	==>	disable OCP for channel 2.
CURRENT3:PROT:TRIG ON	==>	enable OCP for channel 3.
CURR2:PROT:TRIGGER ON	==>	enable OCP for channel 2.
CURR1:PROTECTION:TRIG OFF	==>	disable OCP for channel 1.
CURR:PROTECTION:TRIG OFF	==>	disable OCP for channel 1.
OCP2 ON	==>	enable OCP for channel 2.
OCP3 OFF	==>	disable OCP for channel 3.

**Q63. 如何設定程式?**

PROG 10	==>	define program 10
PROG:ISET1 1	==>	set max. output current of 1A for ch1
PROG:ISET2 1	==>	set max. output current of 1A for ch2
PROG:ISET3 1	==>	set max. output current of 1A for ch3
PROG:VSET1 1	==>	set output voltage of 1V for ch1
PROG:VSET2 1	==>	set output voltage of 1V for ch2
PROG:VSET3 1	==>	set output voltage of 1V for ch3
PROG:FAST 4	==>	output above setting for 4 ms
PROG:NEXT:NEXT	==>	go on to program 11
PROG?	==>	read back the setting of program 10 for verification
PROG 11	==>	define program 11
PROG:ISET1 1	==>	ch1 output up to 1 A
PROG:ISET2 1	==>	ch2 output up to 1 A
PROG:ISET3 1	==>	ch3 output up to 1 A
PROG:VSET1 3	==>	ch1 output 3V
PROG:VSET2 3	==>	ch2 output 3V
PROG:VSET3 3	==>	ch3 output 3V
PROG:FAST 100	==>	output above setting for 100 ms
PROG:NEXT:JUMP 13	==>	jump to program 13
PROG 12	==>	define program 12
PROG:ISET1 1	==>	ch1 output up to 1 A
PROG:ISET2 1	==>	ch2 output up to 1 A
PROG:ISET3 1	==>	ch3 output up to 1 A
PROG:VSET1 5	==>	ch1 output 5V
PROG:VSET2 5	==>	ch2 output 5V
PROG:VSET3 5	==>	ch3 output 5V
PROG:FAST 500	==>	output above setting for 500 ms
PROG:NEXT:END	==>	end the program
PROG 13	==>	define program 13
PROG:ISET1 1	==>	ch1 output up to 1 A
PROG:ISET2 1	==>	ch2 output up to 1 A
PROG:ISET3 1	==>	ch3 output up to 1 A
PROG:VSET1 7	==>	ch1 output 7V
PROG:VSET2 7	==>	ch2 output 7V
PROG:VSET3 7	==>	ch3 output 7V
PROG:FAST 1000	==>	output the setting of program 13 for 1 second
PROG:NEXT:JUMP 12	==>	jump to program 12

**Q64. 如何打開或是關閉 DHCP 狀態?**

CONT:DHCP ON	==>	enable DHCP
CONTROL:DHCP 1	==>	enable DHCP
CONT:DHCP 0	==>	disable DHCP
CONTROL:DHCP OFF	==>	disable DHCP

**Q65. 如何得到 IP 位址?**

CONT:IP?	==>	return IP address
CONTROL:IP ?	==>	return IP address

**Q66. 如何設定 IP 位址?**

CONT:IP 192.168.10.1	==>	set up the IP address
CONTROL:IP 192.168.10.1	==>	set up the IP address

**6.6 狀態定義的規則**

byte 0:	bit 7	channel 3 on/off status
	bit 6	channel 2 on/off status
	bit 5	channel 1 on/off status
	bit 4	channel 3 OVP setting flag
	bit 3	channel 2 OVP setting flag
	bit 2	channel 1 OVP setting flag
	bit 1	channel 3 OCP setting flag
	bit 0	channel 2 OCP setting flag
byte 1:	bit 7	channel 1 OCP setting flag
	bit 6	output mode status; 0: single output 1: multi-output
	bit 5	power on status,0:output off,1: rember pre-setting status
	bit 4	hot-key flag
	bit 3	serial output mode
	bit 2	parallel output mode
	bit 1	track output mode
	bit 0	beep trigger flag
byte 2:	bit 7	disable remote mode, inhib communication
	bit 6	programmable flag
	bit 5	remote flag

	bit 4	keypad between push and pop status
	bit 3	machine running at time mode
	bit 2	machine running at sub-menu mode
	bit 1	machine running at configuration sub-menu mode
	bit 0	machine running at memory item mode
byte 3:	bit 7	machine running at power on status
	bit 6	keypad & Rotary lock flag
	bit 5	machine running at EPROM write or read mode
	bit 4	machine running at synchize mode
	bit 3	display I/V or W/ohm flag
	bit 2	machine running at LCD process mode
	bit 1	detect double- key flag
	bit 0	machine running at key-pad process mode
byte 4:	bit 7	reserved
	bit 6	reserved
	bit 5	reserved
	bit 4	channel 3 OVP is occur flag
	bit 3	channel 2 OVP is occur flag
	bit 2	channel 1 OVP is occur flag
	bit 1	channel 3 OCP is occur flag
	bit 0	channel 2 OCP is occur flag
byte 5:	bit 7	channel 1 OCP is occur flag
	bit 6	relay switch flag
	bit 5	in line system program flag
	bit 4	password is correct flag
	bit 3	machine running at DAC read-back mode
	bit 2	timer pasue flag
	bit 1	machine running at calibration mode
	bit 0	reserved
byte 6:	bit 7	display lock message flag
	bit 6	continue to send "V/I,status" message flag
	bit 5	reserved
	bit 4	reserved
	bit 3	DHCP on or off flag

bit 2      when the bit is on,LCD to display minus('-') signal  
bit 1      fast-output flag  
bit 0      when the machine is OEM version,the flag must on

byte 7:    fan PWM value.


## 7. 校正步驟

### 7.1 校正儀器需求

- \* 6 位半以上規格的三用電表
- \* 三用電表本身的電流檔內阻不可過大,否則會導致電流量測不準確!
- \* CH3 的電流為 5A,故要確定電表有 5A 以上的電流檔,否則會造成電表燒毀!

#### 7.1.1 如何進入 CH1 校正模式：同時按下”飛梭旋鈕” + 數字鍵”1”

### CH1 電壓校正接線圖




- 首先會先進入 CH1 電壓校正畫面,PPS3210-MO 會先輸出一個低電壓,這時在電表上也會同時顯示實際輸出的低電壓值,請將電表上的讀值輸入到 PPS3210-MO 內,按下飛梭鍵確認!緊接著此時會跳下一個畫面,PPS3210-MO 會輸出高電壓,這時在電表上也會同時顯示實際輸出的高電壓值,將電表上的讀值輸入到 PPS3210-MO 內,按下飛梭鍵確認!這時候 CH1 電壓就已經校正完畢!緊接著依照 CH1 電流校正接線圖來接線!

## CH1 電流校正接線圖

**\*記得將電表切換到電流量測畫面\***


電流顯示值



- 再來進入 CH1 電流校正畫面,PPS3210-MO 會先輸出一個低電流,這時在電表上也會同時顯示實際輸出的低電流值,將電表上的讀值輸入到 PPS3210-MO 內,按下飛梭鍵確認! 緊接著此時會跳下一個畫面,PPS3210-MO 輸出高電流,這時在電表上也會同時顯示實際輸出的高電流值,將電表上的讀值輸入到 PPS3210-MO 內,按下飛梭鍵確認!這時候 CH1 電流就已經校正完畢!

## 7.1.2 如何進入 CH2 校正模式：同時按下”飛梭旋鈕” + 數字鍵”2”

## CH2 電壓校正接線圖




- 首先會先進入 CH2 電壓校正畫面,PPS3210-MO 會先輸出一個低電壓,這時在電表上也會同時顯示實際輸出的低電壓值,請將電表上的讀值輸入到 PPS3210-MO 內,按下飛梭鍵確認!緊接著此時會跳下一個畫面,PPS3210-MO 會輸出高電壓,這時在電表上也會同時顯示實際輸出的高電壓值,將電表上的讀值輸入到 PPS3210-MO 內,按下飛梭鍵確認!這時候 CH2 電壓就已經校正完畢!緊接著依照 CH2 電流校正接線圖來接線!

## CH2 電流校正接線圖

**\*記得將電表切換到電流量測畫面\***


電流顯示值



- 再來進入 CH2 電流校正畫面,PPS3210-MO 會先輸出一個低電流,這時在電表上也會同時顯示實際輸出的低電流值,將電表上的讀值輸入到 PPS3210-MO 內,按下飛梭鍵確認! 緊接著此時會跳下一個畫面,PPS3210-MO 輸出高電流,這時在電表上也會同時顯示實際輸出的高電流值,將電表上的讀值輸入到 PPS3210-MO 內,按下飛梭鍵確認!這時候 CH2 電流就已經校正完畢!

### 7.1.3 如何進入 CH3 校正模式：同時按下”飛梭旋鈕” + 數字鍵”3”

## CH3 電壓校正接線圖




- 首先會先進入 CH3 電壓校正畫面,PPS3210-MO 會先輸出一個低電壓,這時在電表上也會同時顯示實際輸出的低電壓值,請將電表上的讀值輸入到 PPS3210-MO 內,按下飛梭鍵確認!緊接著此時會跳下一個畫面,PPS3210-MO 會輸出高電壓,這時在電表上也會同時顯示實際輸出的高電壓值,將電表上的讀值輸入到 PPS3210-MO 內,按下飛梭鍵確認!這時候 CH3 電壓就已經校正完畢!緊接著依照 CH3 電流校正接線圖來接線!

## CH3 電流校正接線圖

**\*記得將電表切換到電流量測畫面\***

電流顯示值



- 再來進入 CH3 電流校正畫面,PPS3210-MO 會先輸出一個低電流,這時在電表上也會同時顯示實際輸出的低電流值,將電表上的讀值輸入到 PPS3210-MO 內,按下飛梭鍵確認! 緊接著此時會跳下一個畫面,PPS3210-MO 輸出高電流,這時在電表上也會同時顯示實際輸出的高電流值,將電表上的讀值輸入到 PPS3210-MO 內,按下飛梭鍵確認!這時候 CH3 電流就已經校正完畢!

## 8. 附件一覽表

產品名稱:PPS3210-MO

產品序號:

A.附件組

項目	品名規格	料號	數量	年 月 日 ~ 選處
1.	電源線	ZPO-640MI	1	<input type="checkbox"/> 有 <input type="checkbox"/> 否
2.	紅黑測試線	ZTP-LPSMI-1	3	<input type="checkbox"/> 有 <input type="checkbox"/> 否
3.	中文說明書	ZOMG-3210C	1	<input type="checkbox"/> 有 <input type="checkbox"/> 否

版本號碼 : Ver1.2



**B+K PRECISION TAIWAN INC.**

Addr: 3F., No. 250, Sec. 3, Beishen Road.,  
ShenKeng Dist., New Taipei City 22204, Taiwan

Tel: +886-2-77416699 Fax: +886-2-77416686

<http://www.bkprecision.com.tw>

e-mail: [bktaiwan@bkprecision.com.tw](mailto:bktaiwan@bkprecision.com.tw)

**ZOMG-3210C-1C**